

MARINE OCCURRENCE REPORT

MAN OVERBOARD

FROM THE SMALL TUG "RED FIR NO. 15"
NORTH ARM OF THE FRASER RIVER, BRITISH COLUMBIA
08 MARCH 1994

REPORT NUMBER M94W0018

MANDATE OF THE TSB

The Canadian Transportation Accident Investigation and Safety Board Act provides the legal framework governing the TSB's activities. Basically, the TSB has a mandate to advance safety in the marine, pipeline, rail, and aviation modes of transportation by:

- conducting independent investigations and, if necessary, public inquiries into transportation occurrences in order to make findings as to their causes and contributing factors;
- reporting publicly on its investigations and public inquiries and on the related findings;
- identifying safety deficiencies as evidenced by transportation occurrences;
- making recommendations designed to eliminate or reduce any such safety deficiencies; and
- conducting special studies and special investigations on transportation safety matters.

It is not the function of the Board to assign fault or determine civil or criminal liability. However, the Board must not refrain from fully reporting on the causes and contributing factors merely because fault or liability might be inferred from the Board's findings.

INDEPENDENCE

To enable the public to have confidence in the transportation accident investigation process, it is essential that the investigating agency be, and be seen to be, independent and free from any conflicts of interest when it investigates accidents, identifies safety deficiencies, and makes safety recommendations. Independence is a key feature of the TSB. The Board reports to Parliament through the President of the Queen's Privy Council for Canada and is separate from other government agencies and departments. Its independence enables it to be fully objective in arriving at its conclusions and recommendations.



The Transportation Safety Board of Canada (TSB) investigated this occurrence for the purpose of advancing transportation safety. It is not the function of the Board to assign fault or determine civil or criminal liability.

Marine Occurrence Report

Man Overboard
from the Small Tug "RED FIR NO. 15"
North Arm of the Fraser River, British Columbia
08 March 1994

Report Number M94W0018

Synopsis

Shortly before midnight on 08 March 1994, in good weather conditions, the "RED FIR NO. 15" was downbound with a loaded chip barge in tow in the North Arm of the Fraser River. When the tow was off the Marine Drive Golf Course, the operator heard a scream and, on looking back, saw the deck-hand in the water ahead of the barge. The tow was turned around but the extensive search which was initiated after the operator radioed for assistance failed to locate the deck-hand.

The Board determined that, although the precise reason for the deck-hand falling overboard could not be established, the design of the tug was a contributing factor in that there are no effective handrails or bulwarks on the afterdeck. The deck-hand could not be found because he probably was not wearing any form of flotation device.

Ce rapport est également disponible en français.

Table of Contents

	Page
1.0 Factual Information	1
1.1 Particulars of the Vessel	1
1.2 Description of the Vessel	1
1.3 Description of the Occurrence	2
1.4 Injuries to Persons	2
1.5 Certification	2
1.5.1 Vessel	2
1.5.2 Operator	2
1.6 Personnel	3
1.6.1 History	3
1.6.2 Work Schedule	3
1.7 Weather	3
1.8 Tide and Current	3
1.9 Safety Equipment	3
1.10 Search for the Deck-hand	4
1.11 Cold Water Survival	4
1.12 Other Traffic	4
2.0 Analysis	5
2.1 Fall Overboard	5
2.2 Wearing of Lifejacket	5
2.3 Tug Design	5
3.0 Conclusions	7
3.1 Findings	7
3.2 Causes	7

4.0 Safety Action 9

5.0 Appendices

 Appendix A - Sketch of the Occurrence Area 11

 Appendix B - Photographs 13

 Appendix C - Glossary 15

1.0 *Factual Information*

1.1 *Particulars of the Vessel*

"RED FIR NO. 15"	
Official Number	348397
Port of Registry	Vancouver, B.C. ¹
Flag	Canadian
Type	Tug
Gross Tons ²	14
Length	10.67 m
Draught	2.6 m
Crew	2
Built	1973, Vancouver, B.C.
Propulsion	Two 240 BHP (176 kW) diesel engines driving twin fixed-pitch propellers
Owners	Rivtow Marine Ltd. Vancouver, B.C.

1.2 *Description of the Vessel*

The "RED FIR NO. 15" is of steel construction, built to standard design and is used primarily for towing log booms and barges in the North Arm of the Fraser River. The wheel-house and accommodation are forward of amidships and the engine-room below the wheel-house. The towing winch and bollard are located immediately abaft the wheel-house on the afterdeck. There are no bulwarks or handrails abaft the superstructure, but a foot rail approximately 30 cm high is fitted round the outside of the afterdeck. A raised wooden grating-cum-working platform has been constructed over the working area of the afterdeck at a height of some 20 cm above the deck.

1.3 *Description of the Occurrence*

On 08 March 1994, the "RED FIR NO. 15" was moving the loaded chip barge "RT 1002" from the Crown Zellerbach Kent Street loading berth to the Point Grey tie-up in the North Arm of the Fraser

¹ See Glossary for all abbreviations, acronyms, and definitions.

² Units of measurement in this report conform to International Maritime Organization (IMO) standards or, where there is no such standard, are expressed in the International System (SI) of units.

River. Stemming the flood tide, the tow was making between three and four knots over the ground, with the operator steering. He was navigating by both visual means and by radar. The deck-hand was working on deck. The length of the tow-line to the barge was reportedly about 20 m.

At about 2350³, with the tow off the Marine Drive Golf Course, the operator was alerted by a scream and looked back to see the deck-hand in the water astern of the tug with the barge bearing down on him. Speed was immediately reduced and the unit turned hard-a-round to starboard. A 180° turn was completed, putting the tow onto the reverse course, but the deck-hand could not be located.

A call for assistance was broadcast on very high frequency radiotelephone (VHF R/T) channel 6. The North Fraser River Patrol responded to the call. Coast Guard Radio Station (CGRS) Vancouver was advised and the incident was reported to the Rescue Co-ordination Centre (RCC) in Victoria, British Columbia. A search and rescue operation was implemented; other vessels in the area responded. The search failed to locate the missing deck-hand.

1.4 Injuries to Persons

The missing deck-hand was presumed to have drowned.

1.5 Certification

1.5.1 Vessel

Being less than 15 gross registered tons, the "RED FIR NO. 15" is not required to be inspected by the Ship Safety Branch of the Canadian Coast Guard (CCG).

1.5.2 Operator

The operator of the "RED FIR NO. 15" was not required to be certificated, but he held a Certificate of Competency as Master of a Home-Trade Steamship of under 350 tons, gross tonnage.

³ All times are PST (Coordinated Universal Time (UTC) minus eight hours) unless otherwise stated.

1.6 *Personnel*

1.6.1 *History*

The operator has served as mate and master of tugs operating in British Columbia waters for more than 25 years.

The deck-hand had started his new seafaring career some 3 1/2 months before the accident and, in that time, had spent 42 days working on tugs, including 6 days on the "RED FIR NO. 15". The vessel's owners have on record that the victim was also on board as an observer for two days in October 1993.

1.6.2 *Work Schedule*

The "RED FIR NO. 15" is manned round the clock by two crews working 12-hour shifts: 0600 to 1800 and 1800 to 0600. The operator and, reportedly, the deck-hand were well rested when they reported for duty at 1800, 08 March.

1.7 *Weather*

The weather was reported as being fine and clear with light airs and a calm sea. The visibility was more than 10 miles.

1.8 *Tide and Current*

The tide was flooding at the time of the accident, and the tidal stream had reached a rate of about three knots.

1.9 *Safety Equipment*

The owners require that a lifejacket be worn under certain conditions, including when working on deck, day or night, and reportedly the deck-hand was wearing a lifejacket at the beginning of the trip. Two lifejackets were found on board during the investigation but, as the operator was uncertain as to how many lifejackets had originally been on board, it could not be determined if the deck-hand was wearing one when he fell overboard.

The victim was wearing warm clothing, work gloves and regular work shoes. The shoes were described as being in relatively good condition by members of the victim's family but there was uncertainty as to the composition of the soles. The owners require that shoes with non-slip soles be worn when working on deck.

1.10 Search for the Deck-hand

CGRS Vancouver advised RCC Victoria of the man-overboard report at 2358, 08 March, at which time the "NORTH ARM PATROL" and a small local tug arrived on the scene. Five other vessels were tasked or responded and, over the next three hours, with the assistance of divers and the Vancouver police department, a search for the missing deck-hand was carried out, reaching as far upstream as Mitchell Island, British Columbia. The deck-hand was reported to be a competent swimmer but, when the search was called off at 0300, 09 March, he had not been located.

1.11 Cold Water Survival

The water temperature in the North Arm of the Fraser River was approximately 5°C when checked the next day.

The Sailing Directions for the British Columbia Coast (South Portion), Vol. 1, Fifteenth Edition, 1990, on the subject of "cold water survival" state in part that "in a water temperature of 5°C, persons without thermal protection become too weak to help themselves after about 30 minutes, and after about an hour the chances of survival are slim if rescued."

1.12 Other Traffic

At the time of the accident, there were no other vessels in the immediate vicinity. About 15 minutes before, the tow had passed two vessels, one downbound and one upbound, but no significant residual wake or surge from these vessels was noted.

2.0 *Analysis*

2.1 *Fall Overboard*

No precise reason could be established for the deck-hand falling overboard. Given the good weather conditions and the absence of other traffic in the area, there were no outside factors to affect the vessel's movement in the seaway. However, the deck-hand was inexperienced and had only worked on the "RED FIR NO. 15" for six days. Someone who is new to a vessel and less familiar with that vessel's layout and motion is more likely to lose his footing.

2.2 *Wearing of Lifejacket*

From the information available with regard to the lifejackets on board the "RED FIR NO. 15", it could not be established with certainty if the deck-hand was wearing a lifejacket when he fell overboard. However, given the thoroughness of the search and the fact that neither the deck-hand nor a lifejacket was found during the search, it is considered unlikely that the deck-hand was wearing a lifejacket at the time of the accident.

2.3 *Tug Design*

The vessel's construction incorporates a 30 cm-high foot rail around the edge of the afterdeck, but the effective height over most of her length is reduced to some 10 cm by the wooden working platform built over the deck area. This raising of the working deck level decreases any personnel safety factor that the foot rail could offer in terms of a foothold and lessens its effectiveness in helping a person recover his balance.

3.0 *Conclusions*

3.1 *Findings*

1. The tug was engaged in towing a loaded chip barge on a short tow-line during the hours of darkness.
2. The deck-hand was new to the vessel, inexperienced, and working alone on the afterdeck of the tug.
3. The deck-hand fell overboard into the path of the barge.
4. There are no bulwarks or shipside rails on the afterdeck.
5. The raised working platform on the afterdeck limits the foot rail's usefulness as a foothold.
6. An extensive search of the area failed to locate the deck-hand.
7. The deck-hand was probably not wearing a lifejacket or any other flotation device.

3.2 *Causes*

Although the precise reason for the deck-hand falling overboard could not be established, the design of the tug was a contributing factor in that there are no effective handrails or bulwarks on the afterdeck. The deck-hand could not be found because he probably was not wearing any form of flotation device.


4.0 *Safety Action*

The Board has no marine safety recommendations to issue at this time.


This report concludes the Transportation Safety Board's investigation into this occurrence. Consequently, the Board, consisting of Chairperson John W. Stants, and members Zita Brunet and Hugh MacNeil, authorized the release of this report on 16 August 1995.

Appendix A - Sketch of the Occurrence Area

Appendix B - Photographs



"RED FIR NO. 15"



Layout of afterdeck.

Appendix C - Glossary

B.C.	British Columbia
BHP	brake horsepower
bollard	Post(s) for belaying, fastening and working ropes and lines.
bulwarks	Vertical plating along each side of vessel above weather deck.
C	Celsius
CCG	Canadian Coast Guard
CGRS	Coast Guard Radio Station
cm	centimetre(s)
foot rail	Length of pipe, low to the deck, with expanded metal between regularly spaced supports.
IMO	International Maritime Organization
kW	kilowatt(s)
m	metre(s)
PST	Pacific standard time
RCC	Rescue Co-ordination Centre
SI	International System (of units)
towing winch	Winch for handling and stowing tow-line.
TSB	Transportation Safety Board of Canada
UTC	Coordinated Universal Time
VHF R/T	very high frequency radiotelephone
°	degree(s)

TSB OFFICES

HEAD OFFICE

HULL, QUEBEC*

Place du Centre
4th Floor
200 Promenade du Portage
Hull, Quebec
K1A 1K8
Phone (819) 994-3741
Facsimile (819) 997-2239

ENGINEERING

Engineering Laboratory
1901 Research Road
Gloucester, Ontario
K1A 1K8
Phone (613) 998-8230
24 Hours (613) 998-3425
Facsimile (613) 998-5572

REGIONAL OFFICES

ST. JOHN'S, NEWFOUNDLAND

Marine
Centre Baine Johnston
10 Place Fort William
1st Floor
St. John's, Newfoundland
A1C 1K4
Phone (709) 772-4008
Facsimile (709) 772-5806

GREATER HALIFAX, NOVA SCOTIA*

Marine
Metropolitain Place
11th Floor
99 Wyse Road
Dartmouth, Nova Scotia
B3A 4S5
Phone (902) 426-2348
24 Hours (902) 426-8043
Facsimile (902) 426-5143

MONCTON, NEW BRUNSWICK

Pipeline, Rail and Air
310 Baig Boulevard
Moncton, New Brunswick
E1E 1C8
Phone (506) 851-7141
24 Hours (506) 851-7381
Facsimile (506) 851-7467

GREATER MONTREAL, QUEBEC*

Pipeline, Rail and Air
185 Dorval Avenue
Suite 403
Dorval, Quebec
H9S 5J9
Phone (514) 633-3246
24 Hours (514) 633-3246
Facsimile (514) 633-2944

GREATER QUÉBEC, QUEBEC*

Marine, Pipeline and Rail
1091 Chemin St. Louis
Room 100
Sillery, Quebec
G1S 1E2
Phone (418) 648-3576
24 Hours (418) 648-3576
Facsimile (418) 648-3656

GREATER TORONTO, ONTARIO

Marine, Pipeline, Rail and Air
23 East Wilmot Street
Richmond Hill, Ontario
L4B 1A3
Phone (905) 771-7676
24 Hours (905) 771-7676
Facsimile (905) 771-7709

PETROLIA, ONTARIO

Pipeline and Rail
4495 Petrolia Street
P.O. Box 1599
Petrolia, Ontario
N0N 1R0
Phone (519) 882-3703
Facsimile (519) 882-3705

WINNIPEG, MANITOBA

Pipeline, Rail and Air
335 - 550 Century Street
Winnipeg, Manitoba
R3H 0Y1
Phone (204) 983-5991
24 Hours (204) 983-5548
Facsimile (204) 983-8026

EDMONTON, ALBERTA

Pipeline, Rail and Air
17803 - 106 A Avenue
Edmonton, Alberta
T5S 1V8
Phone (403) 495-3865
24 Hours (403) 495-3999
Facsimile (403) 495-2079

CALGARY, ALBERTA

Pipeline and Rail
Sam Livingstone Building
510 - 12th Avenue SW
Room 210, P.O. Box 222
Calgary, Alberta
T2R 0X5
Phone (403) 299-3911
24 Hours (403) 299-3912
Facsimile (403) 299-3913

GREATER VANCOUVER, BRITISH COLUMBIA

Marine, Pipeline, Rail and Air
4 - 3071 Number Five Road
Richmond, British Columbia
V6X 2T4
Phone (604) 666-5826
24 Hours (604) 666-5826
Facsimile (604) 666-7230

*Services available in both official languages